

660

Customer Complaint

NO GUN EXAMINATION REPORT NUMBER: MODEL: 660
GENERAL CONDITION: NEW R #: 011064
OUTSIDE WORK: SCOPE MOUNTED DATE: 5-17-72
FIRED AMMO TYPE: FROM: LAKEVIEW SPT. SHOP
& CONDITION: SANDY LAKE, PENNA.
PROOP: R.E.P. INSP.: U TEST: 87 GUN #: 106009
HEADING: O.K. CODE: LR = 2/68
BREECH OPENING: CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED:
CHAMBER: O.K. APPROVED:
TEST: No APPROVED:
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

NO BROKEN COMPONENTS. SLIGHT ROUNDING AT EDGE OF CONNECTOR. BURR ON CORNER OF SEAR. GREASE TYPE OF LUBRICATION INSIDE HOUSING & ON SIDES OF TRIGGER. SEAR - CONNECTOR ENGAGEMENT .015 TRIGGER PULL 4 POUNDS.

COMPLAINT: "WHEN THE SAFETY IS RELEASED, IT FIRES."

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION WAS NOT DUPLICATED. THE BURR ON THE SEAR COMBINED WITH TOO HEAVY LUBRICANT PROBABLY BROUGHT ABOUT FAILURE OF CONNECTOR-TRIGGER TO RETRACT AND FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3335

1091
AL 0030021