

## Phillip Reesor

---

**From:** Chamblee, Danny  
**Sent:** 03/12/2004 05:25:53 PM  
**To:** Reesor, Phillip K.  
**CC:** Byrd, Shane R.; Golemboski, Matt R.; Roudabush, Kathy; Underwood, Harold W.  
**BCC:**  
**Subject:** RE: 710 Receiver Insert Test

Phillip,

We need these guns back at your earliest convenience.

I believe that return procedure would be:  
At E-Town  
Enter a transfer to Mayfield SAP location with no SAP transaction  
Give Customer service necessary to prepare a RGA for the total quantity of guns returned.

At Corporate  
Process the RGA to Mayfield

At Mayfield  
Receive the transfer in DMS (updates DMS inventory)  
Process the RGA (updates SAP inventory)

This being the process, the 62 504 returned were not handled properly in SAP (DMS is fine) and we have overpaid excise taxes. To correct, we need an RGA for 62 504 to correct our SAP inventory.

If you have any questions or comments (or know a better way), please let me know.

Thanks,  
Danny Chamblee  
Accounting Manager  
Remington Arms Company, Inc.  
Mayfield Plant  
22 Rifle Trail, PO Box 99  
Hickory, Ky 42051  
Tel: (270)856-4210  
Fax: (270)856-3233  
E-Mail: danny.chamblee@remington.com  
Visit Remington on the Web at remington.com

-----Original Message-----

**From:** Reesor, Phillip K.  
**Sent:** Friday, March 12, 2004 1:04 PM  
**To:** Chamblee, Danny  
**Subject:** RE: 710 Receiver Insert Test

Not sure what the test involves. I will do everything possible to have returnable and sellable guns at the end of the test. Also I have some gun right now that could be returned. I have 7- 30.06 rifles that were sent for the first safety detent test that was never done and I have 6- 30.06 & 6- 270 rifles that were not shot but were drop tested (one with a stripped receiver take-down screw hole).

Phillip

-----Original Message-----

**From:** Chamblee, Danny  
**Sent:** Friday, March 12, 2004 1:24 PM

Subject to Protective Order - Williams v. Remington

BARBER 5.30.06R0000579

ETE00000778