

XHB	Extractor hits bbl															
HI	High															
LO	Low															
LEFT	Left															
RIGHT	Right															
DG	Doesn't Group															
FSST	Front sight tipped															
RSTT	Rear sight tipped															
RSBR	Rear sight base raised															
FSTR	Front sight raised															
FSTL	Front sight loose															
RSTL	Rear sight loose															
MGPT-G	Missing parts at target															
UNCN-G	Uncoded nonconformity at target															
AI-P	Assembly incompelye at proof															
BC-P	Blows cases at proof															
BEB-P	Barrel extension broken at proof															
BLP-P	Blanked primer at proof															
BP-P	Blown primer at proof															
BS-P	Barrel split at proof															
DLOS-P	Doesn't lock over shells at proof															
ESB-P	Ejector sticks back at proof															
FCB-P	Fore-end cracked at proof															
FESO-P	Fore-end shot off at proof															
FF-P	Fails to fire at proof															

Subject to Protective Order - Williams v Remington