- Breech Flash Gun Club
 - Primed hull with STS primer
 - Change to be evaluated between current and 861 (STS) primer to make decision
 - October production schedule needs to be met

ACTION: MARKETING DECISTION TO USE STS MET BEECS OR LEAD STS MIX INTO GUN CLUB PRIMER METALLES.

- o Grand American
 - Best year in recollection for defects (7 PPM)
- CENTERFIRE
 - Manufacturing
 - Slugs (Bonded and Frangible) will stress capacity
 - INS: handloads look promising.
 - New Product Development
 - Core-Lokt Ultra
 - T&P complete = 243/100, 7mm/160
 - 308/168 in ballistics
 - 338WM/225 = jackets being made week of 9/8
 - 25-06 and 260
 - Issues
 - 300 RSAUM/180 = high pressure @ hot
 - Premier Accurrip
 - 7mm/150 Temporary Accuracy spec not necessary
 - o Premier Varmint Accu-Tip
 - 223/55gr bullets on order from Hornady (non boat tail)
 - Tip color change still open as to change method
 - o 6.8 Rem SPC
 - ★ T&P from EX successful except @ Hot
 - Primer leaks, dropped primers
 - Pressure ok
 - Head hardness ok
 - Shell clearance to be changed to make it larger to allow brass to spring back rather than form to chamber
 - New cups to make this design due October 15
 - Next EX run November 1
 - Managed Recoil
 - Hand loading complete
 - 7mm EX run this month
 - Iwo new bullets developed and hand loaded
 - · Accuracy of 7mm not as good as desired
 - 454 Casull
 - Initial EX run complete
 - Shell splits resolved
 - Harder cups being tried to eliminate head expansion/hard extraction
 - Competitors products appear to be loaded to lower pressure