

P. 1 NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 660GENERAL CONDITION: NEWR # : 18582OUTSIDE WORK: NODATE: 9-23-71FIRED AMMO TYPE: -FROM: GUN RACK INC.NORTHUNAEZLAND, PA.

& CONDITION: _____

GUN # : 127166PROOF: R.E.P.INSP. 73TEST: 13CODE: ER-10/68

HEADING: _____

GA./CAL.: 6.5 REM. MAG.BREACH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO BROKEN, DAMAGED COMPONENTS.COMPLAINT: FOLLOWS DOWN.INCIDENT: FOLLOWS DOWN.COMMENTS: ENGAGEMENT OF CONNECTOR & SEAR, O.K.

TRIGGER PULL = 3 LBS. MIN. IS 4 LBS. APPARENTLY THE
STAKE FAILED TO HOLD THE TRIGGER PULL ADJUSTING SCREW,
BEING OUT OF POSITION AND THE SCREW WORKED LOOSE
UNTIL THERE WAS NO LONGER ANY SPRING TENSION TO
RETRACT THE TRIGGER AND CONNECTOR BACK INTO POSITION
UNDER THE SEAR.

10/ AL0030027