

Customer Complaint

A
P. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 660
GENERAL CONDITION: GOOD R #: 23355
OUTSIDE WORK: NO DATE: 11-2-70
FROM: GREENE, N.Y.
FIRED AMMO TYPE: _____
& CONDITION: _____ GUN #: 113447
PROOF: — INSP. — TEST: — CODE: KR = 5/68
HEADING: — GA./CAL.: 243
BREECH OPENING: — CHECKED BY: C. PROSSER
RECOIL SHOULDERS: — APPROVED: _____
CHAMBER: — APPROVED: _____
TEST: FUNCTION ONLY APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

E K
TRIGGER CONNECTOR APPARENTLY WARPED IN HEAT
TREAT (BROKE WHEN STRAIGHTENING WAS ATTEMPTED)
COULD NOT SEAT PROPERLY ON TRIGGER.

S
COMPLAINT: GUN FIRES WHEN SAFETY IS MOVED TO "OFF".

INCIDENT: _____

C
COMMENTS: SEAR, CONNECTOR ENGAGEMENT INCORRECTLY
ADJUSTED AT FINAL ASSEMBLY, PROBABLY BECAUSE
OF WARPED TRIGGER CONNECTOR.



AL 0030034