BARBER - REM DOCSB0017487

Bolt Action Centerfire – Bolt Lock Update Modification Program. Website text

If you own a Model 30 and 30 Express'es

Model 33 and 33 Expresses do not have the feature known as Bolt lock and as such are not part of this program. Should you desire service on your firearm please feel free to call us on our toll free service line @ 800 243.9700 and we will discuss with you the best way to obtain service or go to our repair section of this website to obtain service in the field

Bottom of page: History of firearm link// 10.commandments of safety and course//

6/12/2006 10