BARBER - REM DOCSB0017497



-710

Answer

Yes, the models 721, 722, *600, *660, *XP-100, and 40X are models that will remove the bolt lock for a \$20 charge.

*The 600, 660, and xp-100 where part of an earlier recall and if your 600, 660, and xp-100 are included in this recall and had not been updated your trigger assembly will be replaced to a non-both tock style trigger and safety at no charge.

If you have a 725, 788, Seven, or 710 you do not have a bolt lock safety or the bolt lock does not operate in the same manner.

Question

Is my rimfire rifle affected by this offer?

Answer

No, there are no rimfire rifles involved in the conversion offer.

Question

Why did you put a special section on our website for the bolt tock?

Answer

The internet is the most effective way to reach a large part of the user base with up to date information. In light of the Barber tragedy we thought it was appropriate to remind shooter of firearms safety. In addition we have rolled out other safety related sections (see website):

- 10 commandments course
- Shotgun safety section
- Black powder safety
- Ammunition safety
- Tree stand safety
- Safety product we sell
- Education links for local safety courses

It will be updated with more safety related information on attending basis and the key section will be rotated on the hunting seasons. We are continually marketing quality firearms that can be used reliably. Safety has always been important to Remington Focusing on safety on the website is part of that long term concern.

Question

How do I know if my 600 or 660 has been updated?

Answer

If there is a "V" stamped on the left side of the trigger then it has been updated.

