

Model 600

	Mohawk 600	600 Carbine	Total
Total Units	97,594	94,086	191,680
Last date of production	1979	1967	

Recalled Yes

Date 1979

Estimated Units worked on &lt;40,000

Cost of Repair	"V"	
	Non Updated	Updated
Parts	12.03	12.03
Labor	15	15
Overhead	25	25
Total	52.03	52.03

Estimated Returns %	2.0%	2.0%
---------------------	------	------

Estimated Returns - Units	3,834	3,834
---------------------------	-------	-------

Fee	\$ -	\$ 20
-----	------	-------

Cost	\$ 52	\$ 32
------	-------	-------

Net Cost	\$ 199,462	\$ 122,790
----------	------------	------------

Notes

1979 recall

Product already had a recall on guns made through February 1975

Installed new firecontrol with bolt lock on it.

Production starting in March of 1975 had new f/c with bolt loc

V on fire control means it has been updated

**New Update Program - 2001****February 1975 and prior Production**

A If no "V" on F/C, put a new model 700 F/C in it

B IF "V" on Fire control

1 Clean, lubricate &amp; keep existing fire control and cut off tab - gun in good work

2 Firecontrol altered or state of disrepair - Get new fire control - Part # F91469

3 Have cleaned, keep bolt lock feature and get a video on safe gun handling