- 4 Find problems customer does not want fixed & sign waiter that guit should not be used in current condition March 1975 and Future Production
 - 1 Clean, lubricate & keep exisiting fire contrtol and cut off tab gun to good working condition
 - 2 Firecontrol altered or state of disrepair Get new fire control Part # ₱91469
 - 3 Have cleaned, keep boil lock feature and get a video, on safe gun handling
 - 4 Find problems customer does not wantifixed & sign waiver that gon should not be used in current condition



Subject to Protective Order - Williams v. Remington