

Model 700

Total Units 1,810,331

Last date of production 1982

		Replace 1 hour Model 700 w f/c	Grind 1 hour model 700 w grind and cle
cost per unit	Avg cost per unit		
warranty cost p			
Labor	26.62	\$ 15.00	\$ 15.00
Benefits	11.68 0.438768	\$ 7	\$ 7
Parts	24.84	\$ 12	\$ -
Overhead	48.54	\$ 24	\$ 24
	112	\$ 58	\$ 46
Charge to Firearm Owner		20	20
Remington Pickup		\$ 37.85	\$ 25.58

	Replace	Grind
Estimated Returns %	0.4%	0.6%
Estimated Returns - Units	7,241	10,862
Cost	\$ 274,095	\$ 277,866

New Update Program - 2001**Bolt Lock Gun**

1. Clean, lubricate & keep existing fire control and cut off tab - gun in good working condition
2. Firecontrol altered or state of disrepair - Get new fire control - Part #
3. Have cleaned, keep bolt lock feature and get a video on safe gun handling
4. Find problems customer does not want fixed & sign waiver that gun should not be used in current condit.

Post Bolt Lock Feature

1. Firecontrol altered or state of disrepair - Get new fire control - Part #
2. Have cleaned
3. Find problems customer does not want fixed & sign waiver that gun should not be used in current condit.