

Model 721

Total Units 270,000

Last date of production 1961

cost per unit		Replace 1 hour Model 700 w f/c	Grind 1 hour model 700 w grind and cle
waranty cost per unit	Avg cost per unit		
Labor	26.62	\$ 25.00	\$ 15.00
Benefits	11.68 0.438768	\$ 11	\$ 11
Parts	24.84	\$ 12	\$ -
Overhead	48.54	\$ 24	\$ 24
	<u>112</u>	\$ 72	\$ 50
Charge to Firearm Owner		20	20
Remington Pickup		\$ 52.24	\$ 29.97

	Replace	Grind
Estimated Returns %	0.4%	0.6%
Estimated Returns - Units	1,080	1,620
Cost	<u>\$ 56,418</u>	<u>\$ 48,550</u>

Notes

**New Update Program - 2001****Bolt Lock Gun**

1. Clean, lubricate & keep existing fire control and cut off tab - gun in good working condition
2. Fire control altered or state of disrepair - Get new fire control - Part # 700 Fire Control (Bend Trigger open slot in stock)
3. Have cleaned, keep bolt lock feature and get a video on safe gun handling
4. Find problems customer does not want fixed & sign waiver that gun should not be used in current