## **BARBER - REM DOCSB0017537**

Model	722		
Total Units	150,000		
Last date of production	1961		8
cost per unit waranty cost per unit Labor Benefits Parts Overhead	Avg cost per unit 26.62 11.68 0.438767 24.84 48.54 112	Replace 1 hour Model 780 w f/c \$ 25.00 84 \$ 11 \$ 12 \$ 24 \$ 72	Grind I hour model 700 \$ 15.00 \$ 11 \$ - \$ 24 \$ 50
Charge to Firearm Owner Remington Pickup		\$ 20 \$ 52.24	\$ 20 \$ 29.97
Estimated Returns %		Replace 0.4%	Grind 0.6%
Estimated Returns - Units		600	900
Cost		\$ 31,344	\$ 26,972
Notes	Jpdate Program - 2001		

## New Update Program - 200 Bolt Lock Gun

- Clean, lubricate & keep exisiting fire contrtol and cut off tab gun in good working cor
- 2 Firecontrol altered or state of disrepair Get new fire control Part #
  700 Fire Control (Bend Trigger open slot in stock)
- 3 Have cleaned, keep boit lock feature and get a video on safe gun handling
- 4 Find problems customer does not want fixed & sign waiver that gun should not be us