

Model xp-100

	pre 79 guns made	post 79 guns made	total guns made
Total Units	26,147	29,984	56131

Last date of production 1999

Recalled Yes

Date 1979

Estimated Units worked on &lt;5000

Cost of Repair

Non Updated

Parts 12.03

Labor 15

Overhead 25

Total 52.03

Estimated Returns % 2.0%

Estimated Returns - Units 523

Fee 0

Cost \$ 52.03

Net Cost \$ 27,209

\$ -

\$ 27,209

Notes

Product already had a recall  
Only 221 Fireball's

**New Update Program - 2001  
Bolt Lock Gun**

1. Clean, lubricate & keep existing fire control and cut off tab - gun in good working condition
2. Fire control altered or state of disrepair - Get new fire control - Part #
3. Have cleaned, keep bolt lock feature and get a video on safe gun handling
4. Find problems customer does not want fixed & sign waiver that gun should not be used in current condition