FAULT CATEGORY		NEW CODE	MALFUNCTIONS MODELS
BROKEN PART	M011	M146	FORE END CRACKED
BROKEN PART		M150	GRIP CAP IS DAMAGED
BROKEN PART		M151	ACTION BAR IS BROKEN
BROKEN PART	M029	M152	EJECTOR BROKEN
BROKEN PART		M158	
BROKEN PART		M167	RIB LANDS ARE LOOSE
BROKEN PART	M016	M184	MAGAZINE TUBE SEPARATED FROM RECEIVER
BROKEN PART	M002	M186	ACTION SPRING TUBE FELL OFF
BROKEN PART	M003	M187	BARREL GUIDE STUD MISSING
BROKEN PART	M004	M188	BARREL SUPPORT SEPARATED FROM MAG TUBE
BROKEN PART		M189	CARRIER LATCH IS BROKEN
BROKEN PART	M013	M190	GAS CYLINDER SEPARATED FROM BARREL
BROKEN PART	M054	M210	GAS CYL CRACKED
BROKEN PART	M026	M214	INTERCEPTOR LATCH STUD MISSING
FAULT CATEGORY		NEW CODE	MALFUNCTIONS MODELS
OUT OF SPECS	M001	M101	ACCURACY
OUT OF SPECS	M001 M027	M104	CHAMBER ROUGH / RINGS / TEARS / TIGHT
OUT OF SPECS	M064	M109	DAMAGES CASES BULLETS OR SHELLS
OUT OF SPECS		M112	HEADSPACE IS EXCESSIVE
OUT OF SPECS	M017	M113	MUZZLE DAMAGE
OUT OF SPECS	M032	M121	
OUT OF SPECS	M020	M124	SIGHTS OFF CENTER
OUT OF SPECS	M028	M127	TRIGGER PULL IS OUT OF FACTORY SPECS.
OUT OF SPECS	M058	M128	CHAMBER DIRTY / RUSTY
OUT OF SPECS		M130	HEADSPACE AT MINIMUM
OUT OF SPECS		M132	BLUING SALTS ARE BLEEDING FROM METAL
OUT OF SPECS		M144	ROLL MARKING VISIBLE INSIDE BORE
OUT OF SPECS		M147	FORE END FIT IS TOO TIGHT
OUT OF SPECS		M148	FORE END IS TOO LOOSE
OUT OF SPECS	M007	M157 🎡	
OUT OF SPECS		M159	CHOKE TUBE THREADS ARE DAMAGED
OUT OF SPECS		M162	FIRING PIN HITS PRIMER OFF CENTER
OUT OF SPECS		M164	RECEIVER + EJECTOR IS LOOSE
OUT OF SPECS		M165	
OUT OF SPECS		M166	
OUT OF SPECS OUT OF SPECS		M167	RIB SWEEPS TO THE LEFT RIB SWEEPS TO THE RIGHT
OUT OF SPECS		M197	CHOKE TUBE CONCENTRICITY - BOTTOM BARREL
OUT OF SPECS		M197	CHOKE TUBE CONCENTRICITY - DOT TOW BARREL
OUT OF SPECS		M203	EJECTOR SEAR OUT OF ADJUSTMENT
OUT OF SPECS		M204	EJECTOR SEAR TOO LONG
OUT OF SPECS	Mar.	M209	RAME FACE IS ROUGH/FIRING PIN HOLES RECESSED
OUT OF SPECS	M047	M217	OVER LOCKED
OUT OF SPECS		M218	PREPLAY ON SEAR NOT TO FACTORY SPECIFICATIONS
MISCELLANEOUS		M102	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPAIR
MISCELLANEOUS	M053	M105	CONSIGNED GUN
MISCELLANEOUS		M106	COULD NOT DUPLICATE CUSTOMERS COMPLAINT
MISCELLANEOUS	M062	M107	CREDIT RETURN
MISCELLANEOUS		M108	DAMAGE APPEARS TO HAVE OCCURRED IN TRANSIT
MISCELLANEOUS	M050	M114	NO CORRESPONDENCE
MISCELLANEOUS	M038	M115	NO FAULT FOUND AT BENCH
MISCELLANEOUS	M045	M116	PACKING ERROR
MISCELLANEOUS	M037	M123	SAFETY CONCERN, EXAMINED BY PRODUCT SERVICE
MISCELLANEOUS		M140	ACTION IS DIFFICULT TO OPEN
MISCELLANEOUS		M195	ACTION CLOSES TOO EASILY
MISCELLANEOUS		M200	
MISCELLANEOUS		M211	
MISCELLANEOUS		M212	GUN RECEIVED WITH SAFETY LOCKED OFF
FUNGTION	M044	M110	FAILS TO FIRE
2000000	1999999		

Subject to Protective Order - Williams v. Remington