	Α	В	С	D
916	OUT OF SPECS	M028	M127	TRIGGER PULL IS OUT OF FACTORY SPECS
917	OUT OF SPECS	M058	M128	CHAMBER DIRTY / RUSTY
918	FUNCTION	M010	M129	FAILS TO EXTRACT
919	OUT OF SPECS		M130	HEADSPACE AT MINIMUM
920	FUNCTION	M057	M131	LIGHT OR NO INDENT FROM FIRING PIN
921	OUT OF SPECS		M132	BLUING SALTS ARE BLEEDING FROM METAL
922	OUT OF SPECS	M048	M133	EXTRACTOR MISSING
923	FUNCTION	M033	M134	FAULTY MAGAZINE
924	OUT OF SPECS	111000	M135	TRIGGER CONNECTOR BINDS
925	BROKEN PART		M136	EXTRACTOR IS BROKEN
926	FUNCTION	M009	M137	FAILS TO EJECT
927	FUNCTION	M023	M138	WILL NOT FEED PROPERLY
928	MISCELLANEOUS	101025	M140	ACTION IS DIFFICULT TO OPEN
929	FUNCTION		M141	EXTRACTOR IS CATCHING ON SHELL HEAD
930	FUNCTION	M015	M142	MAGAZINE DIFFICULT TO LOAD
931	FINISH	MULIO	M143	POOR RECOIL PAD TO STOCK FIT
932	OUT OF SPECS		M144	ROLL MARKING VISIBLE INSIDE BORE
$\overline{}$		MODE		BOLT HANDLE FELL OFF. BOLT IS BROKEN
933	BROKEN PART BROKEN PART	M005	M145	FORE END CRACKED
934		M011	M146	
935	OUT OF SPECS		M147	FORE END FIT IS TOO TIGHT
936	OUT OF SPECS		M148	FORE END IS TOO LOOSE
937	FINISH	M012	M149	FORE END MARRED
938	BROKEN PART		M150	GRIP CAP IS DAMAGED
939	BROKEN PART		M151	ACTION BAR IS BROKEN
940	BROKEN PART	M029	M152	EJECTOR BROKEN
941	OUT OF SPECS	M007	M157	CHOKE TUBE CONCENTRICITY
942	BROKEN PART		M158	CHOKE TUBE CRACKED
943	OUT OF SPECS		M159	CHOKE TUBE THREADS ARE DAMAGED
944	OUT OF SPECS		M162	FIRING PIN HITS PRIMER OFF CENTER
945	OUT OF SPECS		M164	RECEIVER - EJECTOR IS LOOSE
946	OUT OF SPECS		M165	RIB DOESN'T ALIGN WITH RECEIVER
947	OUT OF SPECS		M166	RIB IS DAMAGED
948	BROKEN PART		M167	RIB LANDS ARE LOOSE
949	OUT OF SPECS		M167	RIB SWEEPS TO THE LEFT
950	OUT OF SPECS		M169	RIB SWEEPS TO THE RIGHT
951	OUT OF SPECS	M063	M179	BARREL TO RECEIVER MISALIGNMENT
952	OUT OF SPECS		M180	BOLT EXTRACTOR HITS INSIDE CHAMBER
953	FUNCTION	M024	M181	BURR AT RIM AREA OF CHAMBER
954	FUNCTION	M006	M182	CARRIER OUT OF ADJUSTMENT
955	OUT OF SPECS		M183	GAS ORIFICE HOLE IS OVERSIZE
956	BROKEN PART	M01 <b>6</b>	M184	MAGAZINE TUBE SEPARATED FROM RECEIVER
957	MISCELLANEOUS	MQ52	M185	3 SHOT PLUG AT WRONG END OF MAG TUBE
958	BROKEN PART	M002	M186	ACTION SPRING TUBE FELL OFF
959	BROKEN PART	M003	M187	BARREL GUIDE STUD MISSING
960	BROKEN PART	M004	M188	BARREL SUPPORT SEPARATED FROM MAG TUBE
961	BROKEN PART	***************************************	M189	CARRIER LATCH IS BROKEN
962	BROKEN PART	M013	M190	GAS CYLINDER SEPARATED FROM BARREL
963	OUT OF SPECS		M191	GAS HOLES OUT OF POSITION
964	OUT OF SPECS		M193	TRIGGER - CARRIER LATCH TAB IS OUT OF ADJUSTMENT
965	BROKEN PART	M026	M214	INTERCEPTOR LATCH STUD MISSING
966	MISCELLANEOUS	***************************************	M219	CARDBOARD PACKING RING WAS NOT REMOVED
967	MISCELLANEQUIS	5560000. 888000000000000000000000000000000	M220	PISTON/PISTON SEAL INCORRECTLY INSTALLED
968	OUT OF SPECS		M221	RECEIVER FEED CUTS ARE ROUGH
969		990000000 9000000		
	FAULT CATEGORY	OLD CODE	NEW CODE	: MALFUNCTIONS MODELS
971	OUT OF SPECS	M00:	M101	ACCURACY
972	MISCELLANEOUS		M102	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPAIR
973	BROKEN PART		M103	BUTT PLATE / RECOIL PAD IS BROKEN
974	OUT OF SPECS	M027	M104	CHAMBER ROUGH / RINGS / TEARS / TIGHT
975	MISCELLANEOUS		M105	CONSIGNED GUN
976	MISCELLANEOUS		M103	COULD NOT DUPLICATE CUSTOMERS COMPLAINT
310		3000000 30000000	WITOU	COULD NOT BUT EIGHTE GOOTOMENO COMPENSION