

Glen Sietsema

From: Sietsema, Glen D.
Sent: 01/13/2006 07:22:20 AM
To: Doolittle, James F.
CC:
BCC:
Subject: FW: Routing: 301435 Rev PK 1st article.doc

Jim,
Should the SPL side plate first article go through the Met Chem Lab?

It looks like they missed the inspection.
If so let me know where they are and I'll get them inspected.

Glen D. Sietsema
Metallurgical Engineer
Remington Arms Company, Inc.
14 Hoefler Ave.
Ilion, NY 13357
(315) 895-3234 Phone
(315) 895-3407 FAX
glen.sietsema@remington.com
visit us at www.Remington.com

-----Original Message-----

From: Golem, Todd E.
Sent: Friday, January 13, 2006 7:02 AM
To: Sietsema, Glen D.
Cc: Morningstar, Dean E.
Subject: RE: Routing: 301435 Rev PK 1st article.doc

Glen,

I don't believe these went to MetLab. This is why the Met inspector space is blank. The 1st Article is for dimensional only. These are Jim Doolittle's spl parts. He has them.

Regards,
Todd E Golem - QE

-----Original Message-----

From: Morningstar, Dean E.
Sent: Friday, January 13, 2006 6:58 AM
To: Sietsema, Glen D.
Cc: Golem, Todd E.
Subject: RE: Routing: 301435 Rev PK 1st article.doc

Glen,
I just forwarded the electronic document. I did not initiate the first article report.

Please contact Todd Golem on your question below.