GUN#	PROOF TEST
A-1	HAD TO HAMMER BOLT BACK. ( LOT # N220C6523 )
A-2	HAD TO HAMMER BOLT BACK, SIGNS OF LEAKAGE, CASE
	STUCK IN BOLT AND EJECTOR STUCK BACK (LOT # N22006523)
A-3	HAD TO HAMMER BOLT BACK. ( LOT #№220C6523)
A-4	HAD TO HAMMER BOLT BACK, SIGNS OF LEAKAGE, CASE
	STUCK IN BOLT, EJECTOR STUCK BASK AND BOLT HANDLE BROKE OFF. (LOT # N220C6523).
A-5	HAD TO HAMMER BOLT BACK. ( LQT # D15UB0623 )
A-6	HAD TO HAMMER BOLT BACK. (LOT # D150B6023.)
A-7	HAD TO HAMMER BOLT BACK (LQT # D15UB0623)
A-8	HAD TO HAMMER BOLT BACK (LOT # D15UB0623)
A-9	HAD TO HAMMER BOLT BACK. (LOT#0#5UB0623)
A-10	HAD TO HAMMER BOLT BACK. ( LQT.# D45UB0623 )
A-11	HAD TO HAMMER BOLT BACK (LCT#D15UB0623)
A-12	HAD TO HAMMER BOLT BACK. (LQT # D15UB0623 )
A-13	HAD TO HAMMER BOLT BACK. (LOT# D15UB0623)
A-14	ok
GUN#	PROOF TEST
GUN#	FROOMEST
B-1	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623 )
B-2	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-3	HAD TO HAMMER BOLT BACK (LOT # D15UB0623)
B-4	HAD TO HAMMER BOLT BACK, BROKE BOLT HANDLE OFF.
	(LOT # D15UB0623)
B-5	HAD TO HAMMER BOLT BACK (LOT # D15UB0623)
B-6	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-7 B-8	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623) HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-9	HAD TO HAMMER BOLT BACK. (LOT # D150B0623)
B-10	HAD TO HAMMER BOLT BACK. (LOT # D150B0623)
B-10 B-11	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-12	HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )
B-13	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-14	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
	REDO PROOF TEST
A-2	TOOK BOLT FROM B-1 AND PUT IN A-2 HAD TO HAMMER BOLT
<u>.</u>	BACK. (LOT#D15UB0623)
A-4	TOOK BOLT FROM B-2 AND PUT IN A-4 HAD TO HAMMER BOLT
40000	BACK. (LOT # D15UB0623)
,225,522,235,533	300000000000000000000000000000000000000

Subject to Protective Order - Williams v. Remington