

## GUN #

## PROOF TEST

A-1 HAD TO HAMMER BOLT BACK. ( LOT # N220C6523 )  
 A-2 HAD TO HAMMER BOLT BACK, SIGNS OF LEAKAGE, CASE  
 STUCK IN BOLT AND EJECTOR STUCK BACK. ( LOT # N220C6523 )  
 A-3 HAD TO HAMMER BOLT BACK. ( LOT # N220C6523 )  
 A-4 HAD TO HAMMER BOLT BACK, SIGNS OF LEAKAGE, CASE  
 STUCK IN BOLT, EJECTOR STUCK BACK AND BOLT HANDLE  
 BROKE OFF. ( LOT # N220C6523 )  
 A-5 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 A-6 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 A-7 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 A-8 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 A-9 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 A-10 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 A-11 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 A-12 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 A-13 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 A-14 OK

## GUN #

## PROOF TEST

B-1 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 B-2 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 B-3 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 B-4 HAD TO HAMMER BOLT BACK, BROKE BOLT HANDLE OFF.  
 ( LOT # D15UB0623 )  
 B-5 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 B-6 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 B-7 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 B-8 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 B-9 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 B-10 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 B-11 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 B-12 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 B-13 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )  
 B-14 HAD TO HAMMER BOLT BACK. ( LOT # D15UB0623 )

## REDO PROOF TEST

A-2 TOOK BOLT FROM B-1 AND PUT IN A-2 HAD TO HAMMER BOLT  
 BACK. ( LOT # D15UB0623 )  
 A-4 TOOK BOLT FROM B-2 AND PUT IN A-4 HAD TO HAMMER BOLT  
 BACK. ( LOT # D15UB0623 )