GUN#	PROOF TEST
A-1	HAD TO HAMMER BOLT BACK. (LOT # N220C6523)
A-2	HAD TO HAMMER BOLT BACK, SIGNS OF LEAKAGE, CASE
	STUCK IN BOLT AND EJECTOR STUCK BACK (LOT # N220C6523)
A-3	HAD TO HAMMER BOLT BACK. (LOT #N220C6523)
A-4	HAD TO HAMMER BOLT BACK, SIGNS OF LEAKAGE, CASE
	STUCK IN BOLT, EJECTOR STUCK BACK AND BOLT HANDLE BROKE OFF. (LOT # N220C6523)
A-5	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
A-6	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
A-7	HAD TO HAMMER BOLT BACK, (LQT # D15UB0623)
A-8	HAD TO HAMMER BOLT BACK (LOT # D15UB0623)
A-9	HAD TO HAMMER BOLT BACK. (LOT#D#SUB0623)
A-10	HAD TO HAMMER BOLT BACK. (LQT.#.D15UB0623)
A-11	HAD TO HAMMER BOLT BACK (LOT# D15UB0623)
A-12	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
A-13	HAD TO HAMMER BOLT BACK. (LOT# D15UB0623)
A-14	OK
GUN#	PROOFTEST
B-1	HAD TO HAMMER BOLT BACK: (LOT # D15UB0623)
B-2	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-3	HAD TO HAMMER BOLT BACK (LOT # D15UB0623)
B-4	HAD TO HAMMER BOLT BACK, BROKE BOLT, HANDLE OFF.
B-5	(LOT # D15UB0623) HAD TO HAMMER BOLT BAGK (LOT # D15UB0623)
B-6	HAD TO HAMMER BOLT BACK. (LOT # D150B0623)
B-7	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-8	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-9	HAD TO:HAMMER BOLT BACK. (LOT # D15UB0623)
B-10	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-11	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-12	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-13	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
B-14	HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
	REDO PROOF TEST
A-2	TOOK BOLT FROM B-1 AND PUT IN A-2 HAD TO HAMMER BOLT
	BACK. (LOT#D15UB0623)
A-4	TOOK BOLT FROM B-2 AND PUT IN A-4 HAD TO HAMMER BOLT
\$	BACK. (LOT # D15UB0623)
68666	66000000000000000000000000000000000000

Subject to Protective Order - Williams v. Remington