

> Cc: James, Will; Boyles, Derek; Thompson, Jeff; Riley, Gary D.
 > Subject: RE: 8/6/03 Mayfield meeting
 >
 > Here are the items for review.
 >
 > Print Discussions
 > Safety Arm Blank - The arm angle is greater than print requirements, width is to
 narrow on the arm, and the thumb pad is angled downward.
 > Trigger Pull Spring - Free length and wire diameter
 > Sear Return Spring - Wire diameter.
 > Trigger Guard Screw - Outside head profile: radius is too small.
 > Bolt Cam Lock - .060 radius was to be changed to +/- .010 at .070
 > Take Down Screw - Outside head profile: radius is too small. O.D. of head too
 small.
 >
 > Assembly Issues
 > The receiver and bolt cam lock assembly, mag box changes, and the stock fit.
 >
 > A review of our assembly process is needed.
 >
 > Trigger Assembly
 > Brian Rages is needed to set up trigger scan and a review of our process is
 needed.
 >
 > Thanks,
 >
 > Ed Thweatt

-----Original Message-----

From: Stone, Jeff
 Sent: Tuesday, August 05, 2003 7:45 AM
 To: Thweatt, Ed T.
 Cc: Norton, Vince; James, Will
 Subject: 8/6/03 Mayfield meeting
 Importance: High

> Ed, so that Vince I can prepare for the meeting tomorrow, please
 provide us a list of items that we need to address.
 > Thanks,
 > Jeff S