

Scott Franz

From: Stone, Jeff
 Sent: 08/05/2003 10:18:55 AM
 To: Rages, Brian L
 CC: Franz, Scott
 BCC:
 Subject: FW: 8/6/03 Mayfield meeting

Scott, your call.

JS

> -----Original Message-----

> From: Thweatt, Ed T.

> Sent: Tuesday, August 05, 2003 9:59 AM

> To: Stone, Jeff

> Subject: RE: 8/6/03 Mayfield meeting

>

> Yes, if at all possible. We believe this will be a big help.

>

> Ed

>

> -----Original Message-----

> From: Stone, Jeff

> Sent: Tuesday, August 05, 2003 8:22 AM

> To: Thweatt, Ed T.

> Cc: James, Will; Rages, Brian L

> Subject: RE: 8/6/03 Mayfield meeting

>

> Is Brian Rages needed to make this trip also?

>

> -----Original Message-----

> From: Thweatt, Ed T.

> Sent: Tuesday, August 05, 2003 9:18 AM

> To: Stone, Jeff; Norton, Vince

> Cc: James, Will; Boyles, Derek; Thompson, Jeff; Riley, Gary D.

> Subject: RE: 8/6/03 Mayfield meeting

>

> Here are the items for review.

>

> Print Discussions

> Safety Arm Blank - The arm angle is greater than print requirements, width is too narrow on the arm, and the thumb pad is angled downward.

> Trigger Pull Spring - Free length and wire diameter.

> Sear Return Spring - Wire diameter.

> Trigger Guard Screw - Outside head profile: radius is too small.

> Bolt Cam Lock - .060 radius was to be changed to +/- .010 at .070

> Take Down Screw - Outside head profile: radius is too small. O.D. of head too small.

>

> Assembly Issues

> The receiver and bolt cam lock assembly, mag box changes, and the stock fit.

>

> A review of our assembly process is needed.

>

> Trigger Assembly

> Brian Rages is needed to set up trigger scan and a review of our process is needed.

>

Subject to Protective Order - Williams v. Remington

BARBER 5.30.06R0002267

ETE00001266