

Printed on:
~AUTODATE

43 Inspect For Hardness

Operation Step Detail Operation: 43

Step Operation / Step Description

- 1 Inspect For Hardness
- 2 Break Test N/A
- 3 Record Results on Inspection Form
- 4 Stamp Paper Work
- 5 Record Results in Log Book
- 6 If part fails test put hold ticket on load for Met/chem lab to inspect.

Operation Tool Detail Operation: 43

Tool Number Tooling Description

Std ROCKWELL HARDNESS TESTER WITH SMALL PENCIL POST ANVIL

Operation Procedure Notes Operation: 43

Process

Material: ASAI/SAE 1010

Furnace: Microcarb

Notes: Inspect Using Small Pencil Post Anvil

Inspection

Inspection: Hardness

Inspect For: Rockwell Hardness