

Printed on:
~AUTODATE

Dept	Oper	Operation Description	Part Numbers
9132	1	Issue from Crib	19461 200655
8551	35	Wash, Micro-Carb Harden, Oil Quench, Wash	19461 200655
8551	40	Lindberg Draw	19461 200655
8551	43	Inspect for hardness.	19461 200655

		* INSPECT FOR HARDNESS *	
		* MUST STAMP ---> *	
		* * * * *	
		* INITIALS * * * * *	
		* * * * *	
8551	45	Sand Tumble	19461 200655
8502	50	Wash Magna-Flux, Inspect 100%, Demagnetize	19461 200655
		M	
		M M	
		M M	
		M M	
		M Stamp M	
		M M	
		M M	
		M MagnaFlux M	
		M M M M M M M M	
		DELIVER PART # 200655 TO MRP Crib #25	
8551	55	Black Oxide for Identification	19461
		To MRP Crib #29	