

Steve Perniciaro

From: Marley, Matthew M.
Sent: 01/06/2006 07:28:00 AM
To: Doolittle, James F.; Perniciaro, Stephen; Kelly, John W.; Ballo, John R.
CC: Nichols, Scott; Ogrodnik, Frank A.; George, Ronald M.; Parkhurst, James L.; Wright, MaryAnn
BCC:
Subject: FW: Front and Rear Spacers, P/N 301437 and 301439

Gentlemen -

Please be aware that we have not submitted Engineering Samples for Approval and are not scheduled to do so until January 13th. Once Accounting has generated the Standard Costs for these components, Production Order will be issued (prior to part approval). This is a practice that I cannot endorse on a routine basis, but in an effort to meet your implementation date of February 7th, we will make a best effort to satisfy this demand.

As previously communicated, there are no Production Orders on the PMPD side for Part#300687 SPL Trigger and Part#300659 SPL Sear Safety Cam. With 5 weeks away from Project Kick Off these orders need to be generated as soon as possible.

If it is appropriate to have a meeting to understand the levels of current inventory, a ramp up schedule and/or safety stock locations, please feel free to contact me at x3445.

Matt

-----Original Message-----

From: Wright, MaryAnn
Sent: Thursday, January 05, 2006 4:52 PM
To: Marley, Matthew M.
Cc: Curtis, Jennifer; Lewis, Richard J.; Ogrodnik, Frank A.; Parkhurst, James L.; Tucker, Peter L.
Subject: Front and Rear Spacers, P/N 301437 and 301439
Importance: High

To the best of my knowledge, I have input the BOM's and Routings for both of the front and rear trigger housing spacer blanks, our part numbers 301437 and 301439, respectively. I have updated the BOM for the front spacer based upon our current run of parts, and I have eliminated the barrel finish operation from the routings for both parts. Otherwise, the processes are:

the same for 301437 and 91923
the same for 301439 and 91924.

If there are any problems, please let me know. I noticed that when I tried to input more storage locations for the rear spacer, 301439, an error message about this part not maintained in DL came up. I do not know why this occurred. It did not occur for the front spacer, 301437.

Please contact me if you need anything more!

Maryann

Maryann Wright
Engineering Supervisor
Powder Metal Products Division
Remington Arms Company
14 Hoefler Avenue
Ilion, NY 13357