

Run off samples: Trigger Qty = 4500; Sear safety cam Qty=4500; LH side plate Qty=2800	M.Marley
Cost out and plan new SPL components for the ability to scan product through operations in lion for parts used in the runoff	L.Ferreira
Shipped triggers and sears from Engis runoff to UGT. These parts will be used in the Blohm grind run off. Parts received?	Doolittle
Engis Hone 16 hr run off at Remington	J.Doolittle
Roto clip dimensional issues part 300683 safety retaining clip	Diliberto
SPL department number to be 8772	Allen
Run off samples: LH side plate Qty=4600; RH blocker Qty=5000; LH blocker Qty= 200	M.Marley
Investigate potential plating quality issues	Sietsema/ Morningstar
Resolve PPI gaging with Connecticut spring in regard to the safety	Diliberto
Lot certification for inventory of existing fire control	J.Diliberto
Material handling devices	L.Ferreira/ Allen
Run off rivet operation at Liberty tool in Rochester 4/5/05 delivered scheduled after run off	Doolittle
Need test plan for SPL T&P and number of guns required from SKU list developed	Mroz
Develop flow chart for part	Allen