Subject to Protective Order - Williams v. Remington

XH	Extracts hard] 0
XHB	Extractor hits bbl] 0
DG	Doesn't Group] 0
FSST	Front sight tipped	a a
RSTT	Rear sight tipped] 0
RSBR	Rear sight base raised	
FSTR	Front sight raised	
UNCN-G	Uncoded nonconformity at target	
Al-P	Assembly incompleye at proof	Ō
BC-P	Blows cases at proof]
BEB-P	Barrel extension broken at proof	O
BLP-P	Blanked primer at proof	<u></u>
BP-P	Blown primer at proof	0
BS-P	Barrel split at proof	0
DLOS-P	Doesn't lock over shells at proof	0
ESB-P	Ejector sticks back at proof	0
FCB-P	Fore-end cracked at proof	<u>D</u>
FESO-P	Fore-end shot off at proof	G
FF-P	Fails to fire at proof	0
GCSO-P	Gas cylinder shot off at proof	.
GRSO-P	Guide ring shot off at proof	l a g
MCSO-P	Magazine cap shot off at proof) 0 0 0
MSI-P MSM-P	Magnaflux stamp illegible on bbl Magnaflux stamp missing on bbl	0
PP-P	Pierced primer at proof	j o
UNCM-P	Uncoded proof malfunctions	0
	Onough Production	
		4
		ř
	3000	
į		
i i i		
**		
ij		
*		
ىنىڭىيىنى		
	3 · · · · · · · · · · · · · · · · · · ·	
40000		
3000 3000		
33333.	1606/00 2000/00	