

MODEL 710 BASIC JACK FUNCTION TEST					
PROJECT# 241095					
TLW 0010AA					
9/13/00					
Tech.- Jesse Arnold & Bob Lee					
GUN	AMMO	ROUNDS	STEM LOW	BOLT OVERRIDE	F.T.E.
B-11	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40	7		
	REM PRT3006B 165GR	40	7		
	REM R30063 150GR	40	1		
B-12	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40	3		
B-13	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40	4		
B-14	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40			
B-15	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40			
B-16	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			

ET07101

Confidential - Subject to Protective Order
Williams v. Remington

ET07102

	REM PRT3006B 165GR	40				
	REM R30063 150GR	40			1	
B-17	REM R30065 180GR	40				
	REM R30067 220GR	40				
	UMC L30062 150GR	40				
	REM PRT3006B 165GR	40				
	REM R30063 150GR	40				
B-18	REM R30065 180GR	40				
	REM R30067 220GR	40				
	UMC L30062 150GR	40				
	REM PRT3006B 165GR	40				
	REM R30063 150GR	40	1			
B-19	REM R30065 180GR	40				
	REM R30067 220GR	40				
	UMC L30062 150GR	40				
	REM PRT3006B 165GR	40				
	REM R30063 150GR	40				
B-20	REM R30065 180GR	40				
	REM R30067 220GR	40				
	UMC L30062 150GR	40				
	REM PRT3006B 165GR	40				
	REM R30063 150GR	40	1			
	GRAND TOTAL	RDS = 2000	24	2	1	
	MAFUNCTION RATE=	1.35%				
NOTE: BOLT VERY STIFF CLOSING THE BOLT WHEN CHAMBERING A ROUND. DURING TESTING THERE WERE MANY PROBLEMS WITH THE MAG BOX HOUSINGS COMING APART AT THE SPOT WELD. SOME OF THE MALFUNCTIONS MAY BE ATTRIBUTED THE MAG BOX ISSUE						