

MODEL 710 BASIC JACK FUNCTION TEST
 PROJECT# 241095
 TLW 0010AA
 9/13/00
 Tech.- Jesse Arnold & Bob Lee

GUN	AMMO	ROUNDS	STEM LOW	BOLT OVERRIDE	F.T.E.
B-11	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40	7		
	REM PRT3006B 165GR	40	7		
	REM R30063 150GR	40	1		
B-12	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40	3		
B-13	REM R30065 180GR	40		1	
	REM R30067 220GR	40		1	
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40	4		
B-14	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40			
B-15	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40			
B-16	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40			1
B-17	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40			
B-18	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40	1		
B-19	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40			
B-20	REM R30065 180GR	40			
	REM R30067 220GR	40			
	UMC L30062 150GR	40			
	REM PRT3006B 165GR	40			
	REM R30063 150GR	40	1		
GRAND TOTAL		RDS = 2000	24	2	1
MAFUNCTION RATE=		1.35%			

NOTE: BOLT VERY STIFF CLOSING THE BOLT WHEN CHAMBERING A ROUND.
 DURING TESTING THERE WERE MANY PROBLEMS WITH THE MAG BOX HOUSINGS COMING APART AT THE SPOT WELD.
 SOME OF THE MALFUNCTIONS MAY BE ATTRIBUTED THE MAG BOX ISSUE

ET07103