

GUN # C-8
SER#- 71002501

FM 710 TRIAL AND PILOT TEST

3#

PROJECT#241095!

CAL. - 30.06

[illegible]

Coverpg

ET07403

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

Clean & Inspect Checklist, Series C T&P

Model: 710

Project: 241095

Rifle: C-8

TLW #: TLW0300

Date: 12 / 15 / 00

Inspector: Taser

Round Level: 500

☒ Measure Headspace: Min 4.003

☐ Sear Engagement: .0312 .0301 .0304

☒ Trigger Pull: 1st 3.75 2nd 4.0 3rd 4.0 Ave. 3.92

Check the following areas for signs of unusual wear or breakage:

- ☒ Receiver insert
- ☒ Rear surface of Bolt Lugs
- ☒ Check for "galling" on rear of Bolt Lugs
- ☒ Bolt Plug
- ☒ Bolt Plug Insert "ears" on firing pin assembly
- ☒ Check for loose or missing pins - make note and re-stake if necessary
- ☒ Check plastic inserts for cracks or other damage.
- ☒ Firing Pin Head for Looseness.
- ☒ Check Firing Pin Tip for Looseness.
- ☒ Check Take Down Screws for Movement. Show new position relative to original mark.

 Rear	 Middle	 Front
Position after re-torque:		
 Rear	 Middle	 Front

☒ Check Diaz Bracket Screw for looseness.

☒ Check Bolt Stop 51.24T material movement

Take digital photographs, if appropriate, to record unusual wear, damage or other note-worthy observations. List the digital file name for reference along with any comments below.

TLW0300

TESTPLAN_Rev1_C_Series.doc

Remington Confidential

Revision # 1

ET07404