

CAL.- 30.06

#3

ROUNDS AT START- ~~Q~~

[illegible]

Coverpg.

Williams v. Remington

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
- 315 WEST RING ROAD -
ELIZABETHTOWN, KY 42701

Clean & Inspect Checklist, Series C T&P

Model: 710

Project: 241095

Rifle: C-10

TLW #: TLW0300

Date: 12 / 15 / 00

Inspector: Jess C

Round Level: 500

☒ Measure Headspace Min 7.001

☐ Sear Engagement: 0.0261

☒ Trigger Pull: 1st 3.75 2nd 3.75 3rd 4.0 Ave. 3.83

Check the following areas for signs of unusual wear or breakage:

☒ Receiver insert

☐ Rear surface of Bolt Lugs

☒ Check for "galling" on rear of Bolt Lugs

☒ Bolt Plug

☒ Bolt Plug Insert "ears" on firing pin assembly

☒ Check for loose or missing pins - make note and re-stake if necessary

☒ Check plastic inserts for cracks or other damage.

☒ Firing Pin Head for Looseness.

☒ Check Firing Pin Tip for Looseness.

☒ Check Take Down Screws for Movement. Show new position relative to original mark.

 Rear

 Middle

 Front

Position after re-torque:

 Rear

 Middle

 Front

☒ Check Diaz Bracket Screw for looseness.

☒ Check Bolt Stop 5/34T rotation / movement

Take digital photographs, if appropriate, to record unusual wear, damage or other note-worthy observations. List the digital file name for reference along with any comments below.

TLW0300

TESTPLAN_Rev1_C_Series.doc

Remington Confidential

Revision # 1

ET07408