

GUN # C-14

SER#- 71001787

CAL.- 30.06

[illegible]

Coverpg.

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

Clean & Inspect Checklist, Series C T&P

Model: 710

Project: 241095

Rifle: C-14

TLW #: TLW0300

Date: 12 / 15 / 00

Inspector: Jesic

Round Level: 500

- ☒ Measure Headspace Min +.001
- ☒ Sear Engagement: .0323
- ☒ Trigger Pull: 1st. 5.0 2nd. 5.25 3rd. 5.0 Ave. 5.08

Check the following areas for signs of unusual wear or breakage:

- ☒ Receiver insert
- ☒ Rear surface of Bolt Lugs
- ☒ Check for "galling" on rear of Bolt Lugs
- ☒ Bolt Plug
- ☒ Bolt Plug Insert "ears" on firing pin assembly
- ☒ Check for loose or missing pins - make note and re-stake if necessary
- ☒ Check plastic inserts for cracks or other damage.
- ☒ Firing Pin Head for Looseness.
- ☒ Check Firing Pin Tip for Looseness.
- ☒ Check Take Down Screws for Movement. Show new position relative to original mark.

Original Position:  Rear  Middle  Front

Position after re-torque:  Rear  Middle  Front

- ☒ Check Diaz Bracket Screw for looseness.
- ☒ Check Bolt Stop SLIGHT Material Movement

Take digital photographs, if appropriate, to record unusual wear, damage or other note-worthy observations. List the digital file name for reference along with any comments below.

TLW0300

TESTPLAN_Rev1_C_Series.doc

Remington Confidential

Revision # 1

ET07416