

TLW0300Y

M/710 241095 Remington 30064 Ammo  
10 Round Test 11-17-00 Jeff W.

B1 10 rounds ✓ No problems

B2 10 " ✓ " "

B3 10 " ✓ " "

B4 10 " ✓ " "

B5 10 " ✓ " "

B6 10 " ✓ " "

B7 10 " ✓ " "

~~B8~~

B9 10 " ✓ " "

B10 10 " ✓ " "

11-20-00

B11 10 rounds ✓ No Problems

B12 10 " ✓ " " Bolt hard to close

B13 10 " ✓ " "

B14 10 " ✓ " " Grip cap came off  
after 3 rounds

B15 10 " ✓ " "

B16 10 " ✓ " " Grip cap came off  
after 5 rounds

B17 10 " ✓ " "

B18 10 " ✓ " " Grip cap came off  
after 6 rounds

B19 10 " ✓ " "

B20 10 " ✓ " "

83

11/21/00

ET07595

M/710 241085 Remington 30064 Ammo

10 Round Test 11-15-00 Jeff W.

B21 10 rds. ✓ No Problems

B22 10 rds. ✓ " "

B23 10 rds. ✓ " "

B24 10 rds. ✓ " "

B25 10 rds. ✓ " "

B26 10 rds. ✓ " "

B27 10 rds. ✓ " "

B28 10 rds. ✓ " "

B29 10 rds. ✓ " "

B30 10 rds. ✓ " "

83

ET07596