

GUN # - XC 1059
 DATE - 5-20-99
 SHOOTER - JH

M/710 EET SAMPLE RIFLES
 100 ROUND PROOF TEST

TRACKING # TLW 9142G
 PROJECT # 241095

AMMO PRF 30.00 REM			LOT # F24G C0526		
		MALFUNCTIONS	INS.		MALFUNCTIONS
1	1	HEADSPACE		51	1
2	2	HEADSPACE		52	2
3	3	HEADSPACE		53	3
4	4	HEADSPACE		54	4
5	5	HEADSPACE		55	5
6	6	HEADSPACE		56	6
7	7	HEADSPACE		57	7
8	8	HEADSPACE		58	8
9	9	HEADSPACE		59	9
10	10	HEADSPACE ✓		60	10
11	1			61	1
12	2			62	2
13	3			63	3
14	4			64	4
15	5			65	5
16	6			66	6
17	7			67	7
18	8			68	8
19	9			69	9
20	10	HEADSPACE ✓		70	10
21	1	Sear pin seen out of bore control - replaced		71	1
22	2			72	2
23	3			73	3
24	4			74	4
25	5			75	5
26	6			76	6
27	7			77	7
28	8			78	8
29	9			79	9
30	10	HEADSPACE ✓		80	10
31	1			81	1
32	2			82	2
33	3			83	3
34	4			84	4
35	5			85	5
36	6			86	6
37	7			87	7
38	8			88	8
39	9			89	9
40	10	HEADSPACE ✓		90	10
41	1			91	1
42	2			92	2
43	3			93	3
44	4			94	4
45	5			95	5
46	6	Broken connector in fire control replaced w/ one out of 100		96	6
47	7			97	7
48	8			98	8
49	9			99	9
50	10	HEADSPACE ✓		100	10

INS. = Inspected w/ bore scope
 chamber, lugs

Look at firing pin, extractor
 bolt lugs

ET19850