

GUN # A-4

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303

PROJECT # 241314

SERIAL # 71146737

CAL: 300 WIN MAG

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PR	12/19/02	Out of box Inspection	TLW 1303A		
JS	12/22/03	De-torque scope cross Bolt	Front 30 in lb Rear 30 in lb		
BL	12/22/03	Head space	Min .002		
BL	12/22/03	Prong	Bolt right opening	1	1
BL	12/22/03	Head space	Min .002		
JS/BL	12/22/03	Depth front Take down Scope hole			
BL	12/23/03	Firing Pin Indents	would not take raster holder for indents		
JS	12-29-03	Seal/Trigger Engagement	Arg. .0274		
JS	12-29-03	Seal lift	.0152		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Head space	Min +.005	1	2
SW/JS	1/13/04	Prong RO			
SW/JS	1/13/04	Head space after prod	Min +.005		
BL	1/15/04	200rd Basic Jack Funct test	magazine Box hard to take out / Bolt hard to close	200	202
SW/BL	1/13/04	Head space	Min .005		
BL	1-16-04	Shoulder function test	X20 Rds.	20	222
JS/BL	1-19-04	Inspect & Clean	See Inspection sheet		

Logform

ET19976

Confidential - Subject to Protective Order

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-4

TLW #: TLW1303

Date: 01/19/04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min + .005

☒ Sear Engagement: 1st. .02822 2nd. .0271 3rd. .0277

Ave. .0276 spec. .020" to .025" 2031 Eng
.0248

☒ Trigger Pull: 1st. 4.576 2nd. 4.582 3rd. 4.247

Ave. 4.468 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Locking lugs some wear, excessive wear on bolt stop

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: Insert has a defect must be in the mold.

TLW1303

Remington Confidential

ET19977