

CAL: 300 WIN MAG

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303
PROJECT # 241314

CAL. 300 WIN MAG				ROUNDS AT START-0	
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	De-Torque Scope Cross Bolts	Front 35 in lb Rear 30 in lb		
BL	12/22/03	Headspace	Min +.002	1	1
BL	12/22/03	Proof	OK		
BL	12/22/03	Headspace	Min +.002		
JS/BL	12/22/03	Depth Front Take down	new hole		
BL	12/22/03	Firing Pin Indents	.020 - .021 - .021 Avg. .0206		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0316		
JS	12-29-03	Sear 1st	.0143		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min +.004		1	2
SW/JS	1/13/04	Proof Rd			
SW/JS	1/13/04	Headspace after proof	Min +.004		
BL	1/15/04	200rd PRC Jack Func test	Bolt hard to close with S#1 30wm2 / 5 FTE / magazine hard to take from magazine well.	200	202
SW/BL	1/15/04	Headspace	Min .004	20	222
JS	1-16-04	Shoulder function test	X 20 Rds.		
JS/BL	1-19-04	Inspect & Clean	See Inspection sheet		

Logform

Qd
La

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-5

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min +.004

☒ Sear Engagement: 1st. .0295 2nd. .0295 3rd. .0315

Ave. .0301 spec. .020" to .025"

☒ Trigger Pull: 1st. 4.505 2nd. 4.197 3rd. 4.307

Ave. 4.336 spec. 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary. Front take down screw loose

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Locking lugs some wear, bolt stop excessive wear

☒ Inspect stock for any signs of cracking or other

failure.

☒ Other items of

note: magazine Box protruding, receiver insert has a defect must be in the mold

TLW1303

Remington Confidential

ET19979