

CAL: 300 WIN MAG

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303
PROJECT # 241314

				ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	THW 1207A		
JS	12/22/03	De-torque Slope Cross Bolt Screws	Front 20 in Lb Rear 25 in Lb		
BL	12/22/03	Headspace	min +.002		
BL	12/22/03	Proof	Trigger opening Bolt	1	1
BL	12/22/03	Headspace	min +.002		
JS/BL	12/22/03	Depth Front Take	down screw file		
BL	12/22/03	Firing Pin Indents	1020-19-020 Avg. 0196		
JS	12-29-03	Scot/Trigger Engagement	Avg. 0274		
JS	12-29-03	Gear lift	0152		
SV/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace	Min +.003		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min +.004		
SW	1/14/04	200 Rd Basic Jack Function Test		200	202
SW/JS	1/15/04	Headspace	Min +.007		
BL	1-16-04	Shoulder function test	X20 Rds. Shot clean	20	222
JS/BL	1-19-04	Inspect & clean	See Inspection sheet		

Logform

Q. 10. $\frac{1}{2}$ of a number is 10. What is the number?

Confidential - Subject to Protective Order
Williams v. Remington

ET1 9980

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-6

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min + .004

☒ Sear Engagement: 1st .0267 2nd .026 3rd .0268

Ave. .0265 spec. .020" to .025" ⁸³

☒ Trigger Pull: 1st 4.966 2nd 4.841 3rd 4.763

Ave. 4.857 spec. 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Bolt stop worn, some wear on locking lugs

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box protruding, receiver insert has a defect must be in the
model

TLW1303

Remington Confidential

ET19981