

CAL: 300 WIN MAG

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303
PROJECT # 241314

				ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
TS	12/22/03	De-Torque Scope	Cross Bolt screws Front 25 Rear 30		
BL		Headspace	Min +.005		
BL		Proof	OK	1	1
BL	12/22/03	Headspace	Min +.005		
TS/BL	12/22/03	Depth Front Take down screw hole			
BL	12/23/03	Firing Pin Indents	.019 - .025 021 Aug. 0196		
JS	12-29-03	Sew/Trigger Engagement	Arg. 0294		
JS	12-29-03	Sew 1st	.0171		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head spacer	Min +.006		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min +.006		
B Lee	1/15/04	2000 JAC first test	Bolt hard to close with PRSC30WB / magazine hard to take from magazine well / JATE	200	202
SW	1-15-04	Headspace Min +.006		20	222
BL	1-16-04	Shoulder fire	OK		
TS/BL	1-20-04	Clean. Inspect	See Inspection Sheet		

Logform

5

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-21

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: 202

☒ Measure Headspace min+.006

☒ Sear Engagement: 1st. 0294 2nd. 0273 3rd. 0282

Ave. 0283 spec- .020" to .025" 83

☒ Trigger Pull: 1st. 4.323 2nd. 4.604 3rd. 4.608

Ave. 4.512 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. Some wear on bolt face

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Lacking lugs some wear, Bolt stop some wear

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: Magazine Box protruding

TLW1303

Remington Confidential

ET20011