

GUN # A-23

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303

PROJECT # 241314

SERIAL # 71147656

CAL: 300 WIN MAG

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	De-torque Scope	Cross Bolt Screws Front 30 Rear 30		
BL		Head space	Min +.005		
BL		Proof	Tight to open Emblem on bottom of stock fell off	1	1
BL	12/22/03	Head space	Min to .005		
JS/BL	12/22/03	Depth Front Take down	Screw hole		
BL	12/23/03	Firing Pin Indents	.022-.022-.022 Avg .022		
JS	12-29-03	Sear/Trigger Engagement	Avg .0259		
JS	12-29-03	Sear lift	.0178		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min +.006	1	2
SW/JW	1/13/04	Proof Rd			
SW/JW	1/13/04	Head space after proof	Min +.007		
B Lee	1/15/03	200rd JALC Fund test	magazine Box hard to take from magazine well / 11 FTE	200	202
SW	1-15-03	Head space	Min +.007 (Front Takedown screw loose)		
BL	1-16-04	Shoulder Fire	magazine came out / Bolt stop not functioning properly	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection sheet		

Logform

53

ET20014

Confidential - Subject to Protective Order

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-23

TLW #: TLW1303

Date: 01 119 104

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min .001

☒ Sear Engagement: 1st. 0231 2nd. 0233 3rd. 0231

Ave. 0231 spec. .020" to .025"

☒ Trigger Pull: 1st. 5.042 2nd. 5.177 3rd. 5.070

Ave. 5.096 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Bolt stop worn

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box protruding

TLW1303

Remington Confidential

ET20015