

GUN # A-26

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303

PROJECT # 241314

SERIAL # 71148863

CAL: 300 WIN MAG

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PA	12/14/03	Out of box Inspection	TLW 1303A		
JS	12/22/03	Do-Torque Scope	Cross Bolt screws Front 40 Rear 30		
BL		Head space	Min $\pm .002$	1	1
BL		Proof	O.K.		
BL	12/22/03	Head space	Min $\pm .002$		
JS/BL	12/22/03	Depth Front	Take down screw hole		
BL	12/23/03	Firing Pin Indents	.022-.022-.022-Avg .022		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0274		
JS	12-29-03	Sear Lift	.0152		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min $\pm .004$	1	2
SW/JS	1/13/04	Proof Rd			
SW/JS	1/13/04	Head space after proof	Min $\pm .004$	200	202
SW	1/15/04	200 Rd Basic Jack Function Test			
SW	1-15-04	Head space	Min $\pm .004$		
BL	1-16-04	Shoulder Fire	Bolt stop not working properly	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

93

ET20020

Confidential - Subject to Protective Order

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A26

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min+.004

☒ Sear Engagement: 1st .0258 2nd .0265 3rd .0251

Ave. .0258 spec- .020" to .025" **83**

☒ Trigger Pull: 1st 5.075 2nd 5.039 3rd 5.045

Ave. 5.053 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☐ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Bolt stop excessive wear

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box protruding

TLW1303

Remington Confidential

ET20021