

GUN # A-28

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303

PROJECT # 241314

SERIAL # 71148866

CAL: 300 WIN MAG

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW 1303A		
JS	12/22/03	De-Torque Scope Crosshair screws	Front 35 Rear 35		
BL	1	HeadSpace	min +.003		
BL	1	Proof	OK	1	1
BL	12/22/03	HeadSpace	min +.003		
JS/BL	12/22/03	Depth Front takedown screw hole			
BL	12/23/03	Firing Pin Indent	.019 - .020 Avg .0196		
JS	12-29-03	Sear/Trigger Engagement	Arg. .031		
JS	12-29-03	Sear lift	.0138		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	HeadSpace	Min +.005	1	2
SW/JS	1/13/04	Proof Rd			
SW/JS	1/13/04	HeadSpace after proof	Min +.005		
SW	1/15/04	200 Rd Basic Jach Function Test		200	202
SW	1-15-04	HeadSpace - Min +.005	(Front/4 Center Takedown screw loose)		
BL	1-76-04	Shoulder Fire	Bolt stop not functioning properly / 1 FT Feed	20	222
			1 FTE		
JS/BL	1-20-04	Clean & Inspect	See Inspection sheet		

Logform

ET20024

Confidential - Subject to Protective Order

Williams v. Remington

CONFIDENTIAL

Remington Arms Company/Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-28

TLW #: TLW1303

Date: 01/20/04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace mint.005

☒ Sear Engagement: 1st. 030 2nd. 0302 3rd. 0302

Ave. 0301 spec. 020" to 025" Reset Fr

☒ Trigger Pull: 1st. 4.594 2nd. 5.341 3rd. 5.469

Ave. 5.136 spec- 4 lbs to 5.5 lb. 0258

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. Some wear on bolt face

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Locking lugs same wear, bolt stop worn

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine box protruding

TLW1303

Remington Confidential

ET20025