

GUN # A-4

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303

PROJECT # 241314

SERIAL # 71146737

CAL: 300 WIN MAG

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	De-torque Scope Cross Bolt	Front 30 in lb Rear 30 in lb		
BL	12/22/03	Head space	Min .002		
BL	12/22/03	Proof	Bolt tight opening	1	1
BL	12/22/03	Head space	Min .002		
JS/BL	12/22/03	Depth front Take down Scope hole			
BL	12/23/03	Firing Pin Indent	would not take crusher holder for indents		
JS	12-29-03	Sear/Trigger Engagement	Arg. .0274		
JS	12-29-03	Sear lift	.0152		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Head space	Min .005		
SW/JS	1/13/04	Proof R0		1	2
SW/JS	1/13/04	Head space after proof	Min .005		
BL	1/15/04	200rd Basic Jack Funct test	magazine Box hard to take out / Bolt hard to close	200	202
SW/BL	1/15/04	Head space	Min .005		
BL	1-16-04	Shoulder function test	X20 Rds.	20	222
JS/BL	1-19-04	Inspect & Clean	See Inspection sheet		

Logform

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-4

TLW #: TLW1303

Date: 01/19/04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min+.005

☒ Sear Engagement: 1st. .0282 2nd. .0271 3rd. .0277

Ave. .0274 spec. .020" to .025"

☒ Trigger Pull: 1st. 4.576 2nd. 4.582 3rd. 4.247

Ave. 4.468 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: locking lugs some wear, excessive wear on bolt stop

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: insert has a defect must be in the mold.

TLW1303

Remington Confidential

ET20115