

CAL: 300 WIN MAG

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303
PROJECT # 241314

				ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	De-Torque Scope Cross Bolt	Front 35 in lb Rear 30 in lb		
BL	12/22/03	Head space	Min .002		
BL	12/22/03	Proof	OK	1	1
BL	12/22/03	Head space	Min .002		
JS/BL	12/22/03	Depth Front Take down	new bottle		
BL	12/22/03	Firing Pin Indents	.020 - .021 - .021 Avg .0206		
JS	12-29-03	Sear/Trigger Engagement	Avg .0316		
JS	12-29-03	Sear lift	.0143		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Head space Min +.004		1	2
SW/JS	1/13/04	Proof Rd			
SW/JS	1/13/04	Head space after proof	Min +.004		
BL	1/15/04	2000 BASIC Jack Funct test	Bolt hand to close w/in 30 w/m2 / 5 FTE / magazine hand to take from magazine well.	200	202
SW/BL	1/18/04	Head space	Min .004		
JS	1-16-04	Shoulder function test	X 20 Rds	20	222
JS/BL	1-19-04	Inspect & Clean	See Inspection Sheet		

Logform

—

ET20116

Confidential - Subject to Protective Order

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-5

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: 222

- ☒ Measure Headspace min .004
- ☒ Sear Engagement: 1st. .0295 2nd. .0295 3rd. .0315 Ave. .0301 spec: .020" to .025" .0243
- ☒ Trigger Pull: 1st. 4.505 2nd. 4.197 3rd. 4.307 Ave. 4.336 spec- 4 lb. to 5.5 lb.
- ☒ Check Take-Down Screws and Re-tighten if necessary. Front take down screws loose
- ☒ Inspect extractor & bolt face area.
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs some wear, bolt stop excessive wear
- ☒ Inspect stock for any signs of cracking or other failure.
- ☒ Other items of note: magazine Box protruding, receiver insert has a defect must be in the mold

TLW1303

Remington Confidential

ET20117