

AMMO TYPES				LOTS			
		MALFUNCTIONS				MALFUNCTIONS	
1	1	REM PRA300WC	LOT 029JBI	21	1	REM PRC300WC	LOT 410 BBI
2	2			22	2		
3	3			23	3		
4	4			24	4		
5	5			25	5		
6	6			26	6		
7	7			27	7		
8	8			28	8		
9	9			29	9		
10	10			30	10		
11	11			31	11		
12	12			32	12		
13	13			33	13		
14	14			34	14		
15	15			35	15		
16	16			36	16		
17	17			37	17		
18	18			38	18		
19	19			39	19		
20	20	no screw movement		40	20	no screw movement	
		REM PRSC300WB	LOT T25 BBI			REM R300W2	LOT 410 BBI
		MALFUNCTIONS				MALFUNCTIONS	
1	1			21	1		
2	2			22	2		
3	3			23	3		
4	4			24	4		
5	5			25	5		
6	6			26	6		
7	7			27	7		
8	8			28	8		
9	9			29	9		
10	10			30	10		
11	11			31	11		
12	12			32	12		
13	13			33	13		
14	14			34	14		
15	15			35	15		
16	16			36	16		
17	17			37	17		
18	18			38	18		
19	19			39	19		
20	20	no screw movement		40	20	no screw movement	
		REM R300W1	LOT 420 BBI			REM RS300WA	LOT R16E B3523
		MALFUNCTIONS				MALFUNCTIONS	
1	1			21	1		
2	2			22	2		
3	3			23	3		
4	4			24	4		
5	5			25	5		
6	6			26	6		
7	7			27	7		
8	8			28	8		
9	9			29	9		
10	10			30	10		
11	11			31	11		
12	12			32	12		
13	13			33	13		
14	14			34	14		
15	15			35	15		
16	16			36	16		
17	17			37	17		
18	18			38	18		
19	19			39	19		
20	20	no screw movement		40	20	no screw movement	

1 FTE

83

AMMO TYPES			LOTS		
MALFUNCTIONS			MALFUNCTIONS		
1	1	WIN SHV300WM2 LOT RNO2	21	1	FED P300WC LOT 204 J030
2	2		22	2	
3	3		23	3	
4	4		24	4	
5	5		25	5	
6	6		26	6	
7	7		27	7	
8	8		28	8	
9	9		29	9	
10	10		30	10	
11	11		31	11	
12	12		32	12	
13	13		33	13	
14	14		34	14	
15	15		35	15	
16	16	<i>may be hard to pull out</i>	36	16	
17	17		37	17	
18	18		38	18	
19	19		39	19	
20	20	<i>No screw movement</i>	40	20	<i>no screw movement</i>
WIN X30WM2 LOT RNO2			MALFUNCTIONS		
1	1		21	1	
2	2		22	2	
3	3		23	3	
4	4		24	4	
5	5		25	5	
6	6		26	6	
7	7		27	7	
8	8		28	8	
9	9		29	9	
10	10		30	10	
11	11		31	11	
12	12		32	12	
13	13		33	13	
14	14		34	14	
15	15		35	15	
16	16		36	16	
17	17		37	17	
18	18		38	18	
19	19		39	19	
20	20	<i>No screw movement</i>	40	20	
FED 300WGS LOT 304 J153			MALFUNCTIONS		
1	1		21	1	
2	2		22	2	
3	3		23	3	
4	4		24	4	
5	5		25	5	
6	6		26	6	
7	7		27	7	
8	8		28	8	
9	9		29	9	
10	10		30	10	
11	11		31	11	
12	12		32	12	
13	13		33	13	
14	14		34	14	
15	15		35	15	
16	16		36	16	
17	17		37	17	
18	18		38	18	
19	19		39	19	
20	20	<i>No screw movement</i>	40	20	

83

200