

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .005	1	1
SW / BL	2/16/2004	PROOF ROUND			
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .005		
SW/JW/BL	2/16/04	INDENTS			
SW / BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW / BL	2/17/04	ENGAGEMENT	↓ ↓ ↓		
SW / BL	2/17/04	TRIGGER PULL			
TR	2/19/04	200RD JACK Funct.		200	201
JW	2/25/04	500 RD EXT. Pkwr Test		600	701
BL	3/5/04	Clean / Inspection	See Inspection Sheet		

Logform

W

ET21080

Confidential - Subject to Protective Order
Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-7

TLW #: TLW1303

Date: 3 / 5 / 04

Inspector: BL

Round Level: 701

- ☐ Measure Headspace min 1.00
- ☒ Inspect Take Down Screws for loosening. Top screw 1/2 turn - Center screw 1/4 turn 83
- ☒ Sear Engagement: 1st. .0300 2nd. .0301 3rd. .0296 Ave. .0299 spec- .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st. 2nd. 3rd. Ave.
- ☒ Trigger Pull: 1st. 4.958 2nd. 4.645 3rd. 4.528 Ave. 4.710 spec- 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. 2nd. 3rd. Ave.
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Cam surface, Locking Lugs, bolt stop some signs of wear
- ☒ Inspect stock for any signs of cracking or other failure: Stock cracked at center screw hole
- ☒ Other items of note: Torque Top screw at 55 in lb. - Center screw 45 in lb.

TLW1216

Remington Confidential

ET21081