

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK (SAFETY IN FIRE POSITION)		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .004	1	1
SW / BL	2/16/2004	PROOF ROUND			
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .004		
SW/JW/BL	2/16/04	INDENTS			
SW / BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW / BL	2/17/04	ENGAGEMENT			
SW / BL	2/17/04	TRIGGER PULL			
JK	2/19/04	200 Rd JACK Funct.		200	201
JW	2/25/04	500 Rd Ext Endur Test		500	701
BL	3/5/04	Clean/Inspection	See Inspection Sheet		

Logform

— Cu —
— W —

Confidential - Subject to Protective Order
Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-8

TLW #: TLW1303

Date: 3 15 104

Inspector: BL

Round Level: 701

☒ Measure Headspace min .005

☒ Inspect Take Down Screws for loosening. Top screw 1/8 turn - Center screw 1/8 turn 83

☒ Sear Engagement: 1st. .0372 2nd. .0374 3rd. .0375 Ave. .0376 spec. .025" to .030"

☒ Reset Sear Engagement if Required: 1st. .0290 2nd. .0293 3rd. .0285 Ave. .0289

☒ Trigger Pull: 1st. 4.982 2nd. 5.118 3rd. 5.360 Ave. 5.153 spec- 4.5 lb. to 5.5 lb.

☒ Reset Trigger Pull if Required: 1st. 4.590 2nd. 4.451 3rd. 4.481 Ave. 4.507

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs, Bolt stop signs of some wear

☒ Inspect stock for any signs of cracking or other failure: Stock cracked at center screw hole

☐ Other items of note: _____

TLW1216

Remington Confidential

ET21083