

M710 MAGNUM TRIAL AND PILOT TEST 1.1

SERIAL # 71147088

CAL: 300 WIN MAG

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .005	1	1
SW / BL	2/16/2004	PROOF ROUND			
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .006		
SW/JW/BL	2/16/04	INDENTS			
SW / BL	2/17/04	SEAL LIFT	SEE DATA SHEET		
SW / BL	2/17/04	ENGAGEMENT			
SW / BL	2/17/04	TRIGGER PULL			
JK	2/19/04	200 Rd JACK Funct		200	201
JW	2/25/04	500 Rd EXT. Endur Test		500	701
BL	3/8/04	Clean/Inspection	See Inspection Sheet		

Logform

54

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-10

TLW #: TLW1303

Date: 3 18 104

Inspector: BL

Round Level: 701

- ☒ Measure Headspace mint .006
- ☒ Inspect Take Down Screws for loosening. Top screw 1/4 turn - Center 8 turn 83
- ☒ Sear Engagement: 1st. .0340 2nd. .0337 3rd. .0948 Ave. .03416 spec- .025" to .030"
- ☒ Reset Sear Engagement if Required: 1st. .0284 2nd. .0285 3rd. .0284 Ave. .02843
- ☒ Trigger Pull: 1st. 4.726 2nd. 4.853 3rd. 4.945 Ave. 4.841 spec- 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. 2nd. 3rd. Ave.
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs, bolt stop signs of some wear
- ☐ Inspect stock for any signs of cracking or other failure: cracked stock at center screw hole

☐ Other items of

note:

TLW1216

Remington Confidential

ET21087