

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .006		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .006		
SW / SW / BL	2/16/04	INDENTS			
SW / BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW / BL	2/17/04	ENGAGEMENT	↓ ↓ ↓		
SW / BL	2/17/04	TRIGGER PULL			
BL	2/18/04	200rd Jack Funct.		200	201
BL	2/24/04	500rd Ext. Endur Test		500	701
BL	3/8/04	Clean / Inspection	See Inspection Sheet		

Logform

137

ET21094

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-14

TLW #: TLW1303

Date: 3 / 8 / 04

Inspector: BL

Round Level: 701

☒ Measure Headspace min 1.006

☒ Inspect Take Down Screws for loosening. Top screw 1/4 turn - Center screw 1/8 turn 83

☒ Sear Engagement: 1st .0312 2nd .0314 3rd .0315 Ave. .03136 spec- .025" to .030"

☒ Reset Sear Engagement if Required: 1st .0280 2nd .0286 3rd .0289 Ave. .0285

☒ Trigger Pull: 1st 5.535 2nd 5.455 3rd 5.323 Ave. 5.430 spec- 4.5 lb. to 5.5 lb.

☒ Reset Trigger Pull if Required: 1st 4.805 2nd 4.917 3rd 4.823 Ave. 4.848

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs, bolt stop signs of some wear

☒ Inspect stock for any signs of cracking or other failure: cracked stock at center screw hole

☐ Other items of note: _____

TLW1216

Remington Confidential

ET21095