

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .005		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .005		
SW/JW / BL	2/16/04	INDENTS			
SW / BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW / BL	2/17/04	ENGAGEMENT	↓ ↓ ↓		
SW / BL	2/17/04	TRIGGER PULL			
BL	2/19/04	200 Rd JACK func.		200	201
JS	2/27/04	500 Rd Ext Endur Test		500	701
BL	3/9/04	Clean/Inspection	See Inspection sheet		

Logform

3

Confidential - Subject to Protective Order
Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-16

TLW #: TLW1303

Date: 3 / 8 / 04

Inspector: BL

Round Level: 701

☒ Measure Headspace min+.005

☒ Inspect Take Down Screws for loosening. Top no movement - Center screw to turn 83

☒ Sear Engagement: 1st. .0311 2nd. .0304 3rd. .0315 Ave. .031 spec- .025" to .030"

☐ Reset Sear Engagement if Required: 1st. .02792 2nd. .0277 3rd. .0284 Ave. .028

☒ Trigger Pull: 1st. 4.356 2nd. 4.220 3rd. 4.285 Ave. 4.287 spec- 4.5 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1st. 4.877 2nd. 4.658 3rd. 4.646 Ave. 4.727

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Cam surface, Locking Lugs some sign of wear
Bolt stop has excessive wear

☒ Inspect stock for any signs of cracking or other failure: Cracked stock at center screw hole

☐ Other items of note: _____

TLW1216

Remington Confidential

ET21099