

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .004		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .004		
SW/JW/BL	2/16/04	INDENTS			
SW/BL	2/17/04	SEARCH LIFT	SEE DATA SHEET		
SW/BL	2/17/04	ENGAGEMENT	↓ ↓ ↓		
SW/BL	2/17/04	TRIGGER PULL			
BL	2/19/04	200 Rnd Jack Target		200	201
J.S	2/27/04	500 Rnd Ext. Endur Test		500	501
BL	3/9/04	Clean/Inspection	See Inspection Sheet		

Logform

ET21106

Confidential - Subject to Protective Order
Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-20

TLW #: TLW1303

Date: 3 19 104

Inspector: BL

Round Level: 701

☒ Measure Headspace min .004

☒ Inspect Take Down Screws for loosening. Top screw Just a little - center screw 1/2 turn 83

☒ Sear Engagement: 1st. .0231 2nd. .0236 3rd. .0327 Ave. .03246 spec. .025" to .030"

☒ Reset Sear Engagement if Required: 1st. .0290 2nd. .0296 3rd. .0296 Ave. .0294

☒ Trigger Pull: 1st. 5.028 2nd. 4.930 3rd. 4.892 Ave. 4.950 spec- 4.5 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1st. 2nd. 3rd. Ave.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs some sign of wear

☒ Inspect stock for any signs of cracking or other failure: cracked stock at center screw hole

☐ Other items of note:

TLW1216

Remington Confidential

ET21107